

PIRELLI Manutenzione Sistemi Acquisizione - Bug #62

VTs non scrive correttamente dati sensori in setup VDplugin

06/20/2023 02:36 PM - Marco Pesce

Status:	New	Start date:	06/20/2023
Priority:	High	Due date:	06/27/2023
Assignee:		% Done:	0%
Category:		Estimated time:	4.00 hours
Target version:		Spent time:	0.00 hour
Cliente:	7	Serial Number	
Strumento:	31	Strumento:	
Description			
Related issues:			
Related to Support #61: Calcolo rollio in Dewesoft VDplugin			Closed 06/19/2023 06/20/2023

History

#1 - 06/20/2023 02:37 PM - Marco Pesce

- Related to Support #61: Calcolo rollio in Dewesoft VDplugin added

Files

CoordinateSensori in VDplugin.pdf	333 KB	06/20/2023	Marco Pesce
-----------------------------------	--------	------------	-------------